

VILLAGE OF CARROLLTON

IRON / MANGANESE TESTING

1/31/2024

TESTING LOCATION	CHL	I	M
TREATMENT PLANT	1.2 .2	0.00	0.03
COURTVIEW DR	1.1 .3	0.00	0.02
2ND ST SE	1.1 .2	0.00	0.03
CANTON RD	1.1 .2	0.00	0.02
12TH ST	1.2 .1	0.00	0.02
SECONDARY MCL FOR IRON .3 ppm			
SECONDARY MCL FOR MANGANESE .05 ppm			