

VILLAGE OF CARROLLTON

IRON / MANGANESE TESTING

3/19/2024

| TESTING LOCATION | CHL | | I | M |
|-----------------------------|-----|----|---------|------|
| TREATMENT PLANT | 1.2 | .2 | 0.00 | 0.02 |
| COURTVIEW DR | 1.1 | .2 | 0.00 | 0.02 |
| 2ND ST SE | 1.3 | .2 | 0.00 | 0.02 |
| CANTON RD | 1.0 | .3 | 0.00 | 0.02 |
| 12TH ST | 1.2 | .2 | 0.00 | 0.02 |
| SECONDARY MCL FOR IRON | | | .3 ppm | |
| SECONDARY MCL FOR MANGANESE | | | .05 ppm | |