

VILLAGE OF CARROLLTON

IRON / MANGANESE TESTING

4/3/2024

| TESTING LOCATION | CHL | | I | M |
|-----------------------------|-----|----|------|---------|
| TREATMENT PLANT | 1.1 | .1 | 0.00 | 0.02 |
| COURTVIEW DR | 1.1 | .2 | 0.00 | 0.03 |
| 2ND ST SE | 1.0 | .2 | 0.00 | 0.02 |
| CANTON RD | 1.2 | .1 | 0.00 | 0.03 |
| 12TH ST | 1.2 | .1 | 0.00 | 0.02 |
| | | | | |
| SECONDARY MCL FOR IRON | | | | .3 ppm |
| SECONDARY MCL FOR MANGANESE | | | | .05 ppm |